


Cgl



02975.000112

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
: Examiner: M. Budd
KENJIRO TAKEMURA, et al.)
: Group Art Unit: 2834
Application No.: 10/669,429)
:
Filed: September 25, 2003)
:
For: CONTROL APPARATUS FOR)
: VIBRATION TYPE ACTUATOR,)
: VIBRATION TYPE ACTUATOR)
: SYSTEM, AND METHOD FOR)
: CONTROLLING VIBRATION TYPE)
: ACTUATOR)
:
U.S. Patent No.: 6,885,132)
:
Issued: April 26, 2005)
: March 30, 2006

Certificate
APR 04 2006
of Correction

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION UNDER RULE 322

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes. A Certificate of Correction form, in duplicate, is enclosed.

APR - 4 2006

Patentees' undersigned attorney may be reached in our Costa Mesa,
California office by telephone at (714) 540-8700. All correspondence should continue to
be directed to our address given below.

Respectfully submitted,

A handwritten signature in black ink, appearing to read "Michael K. O'Neill", is written over a horizontal line.

Attorney for Patentees
Michael K. O'Neill
Registration No.: 32,622

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
Facsimile: (212) 218-2200

CA_MAIN 111356v1

APR - 4 2006

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,885,132

DATED : April 26, 2005

INVENTOR(S) : KENJIRO TAKEMURA, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4

Line 23, "th" should read --the--.

COLUMN 9

Line 28, "constitut d" should read --constituted--.

COLUMN 12

Line 25, "they-axis" should read --the y-axis"; and

Line 49, "mod 1" should read --model--.

COLUMN 13

Line 64, "Mode₆₀," should read --Mode_a--.

COLUMN 14

Line 27, "fac" should read --face--;

Line 35, "actuator-in" should read --actuator in--; and

Line 56, "inv ntion" should read --invention--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,885,132

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30)

CA_MAIN 111358 v1



APR - 4 2005

Staple
Here
Only!

PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : 6,885,132
DATED : April 26, 2005
INVENTOR(S) : KENJIRO TAKEMURA, et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 4

Line 23, "th" should read --the--.

COLUMN 9

Line 28, "constitut d" should read --constituted--.

COLUMN 12

Line 25, "they-axis" should read --the y-axis"; and
Line 49, "mod 1" should read --model--.

COLUMN 13

Line 64, "Mode₆₀," should read --Mode_α--.

COLUMN 14

Line 27, "fac" should read --face--;
Line 35, "actuator-in" should read --actuator in--; and
Line 56, "inv ntion" should read --invention--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3800
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. 6,885,132

No. of add'l. copies
@ 30¢ per page

Form PTO 1050 (Rev. 3-82)

(Form#30)

CA_MAIN 111358 v1



APR - 4 2000

Staple
Here
Only!

PRINTER'S TRIM LINE